

JET-X™ REBUILD PROGRAM

FOR 750/1380/2250 INTENSIFIERS



The Jet-X™ Rebuild Program is intended for customers who want to retain their own intensifiers but chose not to opt for the Jet-X™ Xchange program. This service is performed at our Montréal facility by our certified technicians, according to the service plan that best suits your needs. A standard process would be as follows:

- Mill technician will replace one or both pump intensifiers with spare unit owned by the mill
- Mill contacts Paprima to advise the intensifier is ready for pick-up
- Paprima organizes the logistics and plans shop service work
- The intensifier is overhauled and tested according to the selected service plan
- Paprima will package and prepare the overhauled unit for return shipment
- Overhauled intensifier can be put in stock for the next replacement

BRONZE

- Replacement of all seals and o-rings
- Replacement of footvalve
- Complete visual inspection
- Functionality test
- 90-day warranty

SILVER

- Bronze plan included
- Replacement of all fittings, tie-rods, nuts & bolts
- New proximity switch
- New solenoid valve
- Complete dimensional inspection of all critical dimensions with report
- Reassemble, pressurization test & report
- 120-day warranty

GOLD

- Silver plan included
- NDT of all oil/water cylinder components
- NDT of intensifier piston
- Replacement of footvalve seating ring
- Replacement of any defective part
- Oil sample analysis
- Complete NDT report
- 180-day warranty

Note: Unless requested, all replaced components will be kept at Paprima for 90 days and then recycled.

